



Dear 3 Chisolm Homeowners:

September 17, 2018

We escaped major damage from Hurricane Florence for which we are all grateful. Thanks to the hard work of Richard Simons, our property manager implemented the hurricane procedure the board worked on this last year.



The photo above shows one barrier over the crawl space vents that was put in place as part of our hurricane procedure. All crawl space vents were covered.

The photos below illustrate the system for mitigating flood water intrusion at all entry doors. The gym building, being elevated, has sand bags in place. The main building entry doors, including the garden doors, have the floor control system in place developed over the past year.





When a hurricane is threatening, the property manager will implement this procedure. Entry to the main building is through the center staircase off Chisolm street that leads to the second floor. IF YOU DO NOT HAVE A KEY TO THIS DOOR, PLEASE CONTACT THE PROPERTY MANAGER.

We thank, Tommy Knisley, our property manager for his tireless attention to our building's safety. We also thank Richard Simons for designing and working on this project.

Your Sincerely,

3 Chisolm Regime Board of Directors